

BRITISH WIRING INC.

P.O. BOX 185

617 WALNUT STREET

BALLY, PA 19503

Toll Free: 866-461-9050

Fax: 610-845-3518

[e-mail: britishwiring@ameritech.net](mailto:britishwiring@ameritech.net)[web page: www.britishwiring.com](http://www.britishwiring.com)

	Wire	Wrap	Description
	B	B	Braided wire and Braid outer wrap.
	P	P	PVC wire and PVC tape outer wrap.
	P	B	PVC wire and Braid outer wrap.
	PB	B	Mixture of PVC & Braided wire & Braid outer wrap.
	PB	P	Mixture of PVC & Braided wire & PVC outer wrap.

Choose - Headlamp Pigtails for the Models in this Listing - need 2 per car

Part #	Wire	Wrap	Pcs	Wrap	Blue/White (UW) wire	Blue/Red (UR) wire	Black (B) ground wire
141	P	P	1	PVC	PVC	PVC	PVC
141 XP	PB	P	1	PVC	Braid	Braid	PVC
141 XB	PB	B	1	Braid	Braid	Braid	PVC
141 BB	B	B	1	Braid	Braid	Braid	Braid

Alternator Conversion

ALT	-	-		All	Any model, factory conversion of harness from generator to alternator.		
-----	---	---	--	------------	--	--	--

TALBOT

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
ST27C	B	B	3	50/54	Talbot 90, Mk 2, 2A - A 3,000,001 - on, LHD	Complete

TALBOT ALPINE

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
282	B	B	3	53/54	Mk 1, 2, 2A - LHD	Complete
284	B	B	3	55/57	Mk 3 - LHD	Complete

ALPINE

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
1571	P	B	2	59/60	Series 1 - B 9,000,001 - on	Complete
1571	P	P	2	60/62	Series 2 - B 9,100,001 - on	Complete
1575	P	P	2	63/64	Series 3 - B 9,200,001 - on	Complete
1577	P	P	2	1965	Series 4 - B 9,400,001 - on	Complete
1579	P	P	3	65/67	Series 5 - B 395,000,001 to 395,019,022, Alternator model	Complete
1590	P	P	2	59-67	Series 1 to Series 5 - Overdrive harness set	

TIGER

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
1581	P	P	2	64/65	Mk 1 - 9,470,001 - on	Generator model Complete
1582	P	P	2	65/66	Mk 1A - B382,000,001 to B382,002,694	Generator model Complete
1583	P	P	2	1966	Mk 2 - B382,100,001 to B382,100,633	Alternator model Complete

Note: 1571 has an odd routing - doubles back on itself at one point - it is how the original was!

Note: 1583 can not be used for a Mk1A that has been converted to an alternator. Need to special order a 1582 ALT